



NOTE: For all analyses at this site, groundwater is assumed to be 0.7 m below the ground surface.

KEY

Pre-improvement CPT-	CPT 12			Unlikely to liquefy		Potential to liquefy
	CPT 13			Depth of Improvement (0 - 3m)		
Post-improvement CPT-	CPT 34					
	(1.5m)					
	CPT 35					
	(2.0m)					
	CPT 36					
	(2.5m)					
	CPT 37					
	(3.0m)					



Ground Improvement Spacing Trials
 Site 4 (Avondale)
 Low Mobility Grout
 27 Day Post Improvement CPT

Location: Site 4
 Job No.: 52020.021
 Version No.: 2.1
 Figure: 6D4

Date: 16/07/2013
 Analysed by: KGN
 Checked by:

DRAFT