


NOTE: For all analyses at this site, groundwater is assumed to be 0.6 m below the ground surface.



KEY

Pre-improvement CPT-	CPT 28			Unlikely to liquefy		Potential to liquefy
	CPT 29			Depth of Improvement (0 - 3m)		
Post-improvement CPT-	CPT 44					
	(1.5m)					
	CPT 45					
	(2.0m)					
	CPT 46					
	(2.5m)					
	CPT 47					
	(3.0m)					



Ground Improvement Spacing Trials
 Site 6 (Bexley)
 Low Mobility Grout
 28 Day Post Improvement CPT

Location: Site 6
 Job No.: 52020.021
 Version No.: 2.1
 Figure: 6D6

Date: 16/07/2013
 Analysed by: KGN
 Checked by:

DRAFT