



KEY

- CPT 22 (orange line)
- CPT 23 (blue line)
- CPT 24 (green line)
- CPT 25 (red line)
- SWS 001 (orange circle)
- SWS 09 (blue circle)
- SWS 10 (green circle)
- SWS 11 (red circle)
- SWS 03 (red circle)
- SWS 04 (green circle)
- SWS 05 (blue circle)
- SWS 06 (teal circle)
- SWS 07 (red circle)
- SWS 08 (dark blue circle)

■ Potential to liquefy (red)
 ■ Unlikely to liquefy (green)

Sept '10 Event	PGA = 0.19g	Mw = 7.1
Feb '11 Event	PGA = 0.40g	Mw = 6.2
June '11 Event	PGA = 0.25g	Mw = 6.2



Ground Improvement Trials
Site 6 (Bexley)
 T-Rex Test Area Ground Conditions

Location: Site 6
 Job No.: 52020.021
 Version No.: 2.1
 Figure No.: 3F6

Date: 16/07/2013
 Analysed by: KGN
 Checked by:

DRAFT