

**LEGEND**

LPI

- Street level mapping undertaken with no observed liquefaction or ground cracking
- 0 - 3 Observation of liquefaction from ground based street level mapping
- 3 - 6 Observation of liquefaction from aerial fly over mapping
- 6 - 9
- 9 - 12
- 12 - 15
- 15 - 18
- 18 + Observation of Flooding
- Observation of Ground cracking

Notes:  
The land based observation did not cover the entire area where liquefaction was known to have occurred.


This map presents a compilation of verified observations of liquefaction by team of engineers on the afternoon of 23 Dec 2011.

Date: 5/03/2013 Time: 10:43:51 a.m.

Notes: Road Database supplied by Terralink International Ltd. Rivers, lagoons and coastline licensed under Creative Commons Attribution 3.0 New Zealand and sourced from LINZ. Crown Copyright Reserved

A3 SCALE 1:60,000

0 1 2 3 4 (km)



**EQC**  
EARTHQUAKE COMMISSION  
Kōmihana Rūwhenua

|                                  |     |        |
|----------------------------------|-----|--------|
| DRAWN                            | CXP | Mar.13 |
| CHECKED                          |     |        |
| APPROVED                         |     |        |
| ARCFILE                          |     |        |
| 52020-0200-LSN236                |     |        |
| SCALE (AT A3 SIZE)               |     |        |
| 1:60,000                         |     |        |
| Prepared by Tonkin & Taylor Ltd. |     |        |
| Ref: 52020-0200                  |     |        |

EARTHQUAKE COMMISSION  
CHRISTCHURCH CITY & KAIAPOI  
LPI, December 2011  
(Using Cornell PGA)

FIGURE No.  
Figure F53

Rev. 0